

# SC - Hot Melt Type Quickly Assembly Connector

## **DESCRIPTION**

Hot-melt quickly assembly connector is directly with a grinding of the ferrule connector directly with the butterfly cable 3.0mm,2.0mm,0.9mm using a fusion splicer welding,the welding point inside the connector tail, the weld is no need for additional protection. It can improve the optical performance of the connector.

#### **FEATURES**

- · Apply for FTTH optical fiber
- · Fast and live connecting
- · The same function as standard optical connector
- · Without redundant cable, easy management



#### **APPLICATIONS**

- $\rightarrow$  FTTx/FTTH
- → Optical Fiber Socket Panel

### **SPECIFICATIONS**

Parameters	Value	Parameters	Value
Insertion Loss	Average ≤0.3 DB, max≤0.5 DB	Repeatability (500 Mating Times)	Average ≤0.3 DB, max ≤0.5 DB
Return Loss	≥ 45dB	Temperature cycle	
Tensile strength	F>50N	Vibration test	
Operating Temperature	-20 ~ +75°C	Flooding test	
Storage Temperature	-40 ~ +85°C	Tensile strength	F>50N